

TLC BEFORE

AFTER—as of SEPT 2010

Asbestos removed from windows, floor tiles, ceiling plaster.

Basement cleared of all debris, Exterior Shed removed, Temporary red paint on plywood window coverings to cheer up back of building while under construction.




TLC Main St construction shed , new opening, tin ceiling detail

2nd fl Gallery—cleared, temporary window lights installed

3rd fl Studio—cleared, temporary windows installed for air and light; 3rd floor office area painted.



2nd floor Gallery



3rd floor Studio

Third floor Studio now cleared, office space cleared, above. Stairwell, new door, with restored arched light, under construction below.



two extremely heavy safes to remove from the middle of the third floor. IDEAS?

