

Tahawus Lodge Center — as of Nov 1, 2010



Window Store front and Show room

Glass windows installed.
Interior show room
awaits foam insulation,
ceiling tin to be re-
placed, and new floor
to be installed.

Entry way granite to be
laid.



Conceptual sketch showing Window Gallery Store front room



2nd floor Gallery



New basement
stair case
with landing